MARION COUNTY SURVEYOR'S OFFICE

DEBRA S. JENKINS MARION COUNTY SURVEYOR SECTION CORNER RECORD SEC. $15\,\mathrm{TWN}$. $17_{\,\mathrm{N}}$ RNG. $4_{\,\mathrm{E}}$

BRYAN F. CATLIN, PLS TECHNICAL SUPERVISOR

Date: 5-12-09

Party Chief: Wilcoxen

Crew: Finney

Type of Marker: Harrison

Method of Establishment: County: 8-15-95

IN S.P.C. E Zone, NAD 83

Name: 17041505 N: 518 679.668 7 (m) E: 66 356.511 0(m) E. 91st St 9100 N

E. 91st St 9100 N

5. 830

4. 126.23'

3. 2.

Survey by Smith 12-6-1877 called rock marker with witnesses: 14" white hickory S 52 1/4 E 70 links, 8" sugar S 23 1/2 E 65 links per Lawrence Township Legal Survey book pg 29. MCSO reference (no date) did not call out marker. Monroe 7-28-60 called a steel pin over stone 3" down. Wilcoxen 4-20-76 called a brass plug in steel box. Gries 2-17-89 called the same. Excavated by Wilcoxen 8-15-95 brass plug fd at surface. Stone fd 12" down. Brass plug fd 0.23' S and 0.15' E of stone. Harrison set. Re-tied 3-5-2000 by Wilcoxen. Re-tied 5-12-09 by Wilcoxen.

REF.	DISTANCE	DESCRIPTION
1.	146.15'	Cut 'x' S Sleeve of PwP #11-216-A 24" up
2.	37.18'	PK nail W PwP #212-216-A 4" up
3.	75.08'	South-East top edge of church brick sign
4.	126.23'	RR spike S PwP #9-216-A 18" up
5.	18.59'	Mag nail S spur root 12" maple

THIS CORNER POSITION
REPRESENTS A "TITLE" CORNER
AND MAY NOT NECESSARILY
REPRESENT THE POSITION BASED
ON RECORD CORNERS.